

Using TI's CDCV304 with Backplane Transceiver (TLK1201, TLK1501, TLK2201, TLK2501, TLK2701, TLK2711, and TLK3101)

Firoj Kabir

HPA/CDC

ABSTRACT

This application note discusses TI's CDCV304 output jitter when driving serial backplane transceivers, namely, TLK1201, TLK1501, TLK2201, TLK2501, TLK2701, TLK2711, and TLK3101. Measurement shows that the CDCV304 clock driver generates 20-ps p-p jitter on average; hence it is suitable to drive any serial backplane transceivers fulfilling all the requirements.

Contents

Introduction	2
Jitter Performance of CDCV304 (Driven by HP8133A Signal Generator)	2
Test Equipment Setup for Driving Backplane Transceiver	4
Recommended Termination for CDCV304 Clock Driver	5
Test Summary	5
Jitter Performance of CDCV304 + TLK1201 Combination	6
Jitter Performance of CDCV304 + TLK1501 Combination	7
Jitter Performance of CDCV304 + TLK2501 Combination	8
Jitter Performance of CDCV304 + TLK3101 Combination	9
Conclusion	9
References	10

Figures

Figure 1.	Indicates Various Jitter Measurement Points	2
Figure 2.	Peak-to-Peak and RMS Jitter of HP Signal Generator (Point 1)	3
Figure 3.	Peak-to-Peak and RMS Jitter of CDCV304 Driver Output (Point 2)	3
Figure 4.	Peak-to-Peak Jitter of CDCV304 Driver Output (Point 2 Over Industrial	
U	Temperature Range)	4
Figure 5.	Test Equipment Setup	4
Figure 6.	Thevenin Termination for CDCV304 Clock Driver	5
Figure 7.	Jitter Values at Different Points Shown in Figure 5 With TLK1201	6
Figure 8.	Jitter Values at Different Points Shown in Figure 5 With TLK1501	7
Figure 9.	Jitter Values at Different Points Shown in Figure 5 With TLK2501	8
Figure 10.	Jitter Values at Different Points Shown in Figure 5 With TLK3101	9

Tables

Table 1. R	ecommended Clock D	rivers for Serial / Gigabit	Transceivers9
------------	--------------------	-----------------------------	---------------



Introduction

This application report discusses various jitter measurements of TI's CDCV304 clock driver. The CDCV304 is a 1:4 low-skew, low-jitter, single-ended LVTTL clock driver. The CDCV304 is characterized for industrial temperature (-40°C to 85°C) and has a maximum operating frequency of 140 MHz. The four output signals are low-skew, low-jitter copies of the input clock. These properties make the CDCV304 ideal for various datacom and telecom applications

Jitter Performance of CDCV304 (Driven by HP8133A Signal Generator)

TI's backplane transceivers require an input reference clock with maximum peak-to-peak jitter of 40 ps and of 40%–60% duty cycle. The worst-case output peak-to-peak jitter of the CDCV304 driver is less than 30 ps over a –40°C to 85°C range at nominal power supply. This characteristic makes the CDCV304 an excellent choice to drive a backplane transceiver at the specified clock frequency.



Figure 1. Indicates Various Jitter Measurement Points

Jitter measurements were taken at point 1 (output jitter of the signal generator and input jitter to the CDCV304 clock driver) and point 2 (output jitter of the HP8133A+CDCV304 combination and input jitter to the backplane transceiver). See Figures 2, 3, and 4 for results.



Jitter vs Frequency (3.3 V, Room Temp, VIH = 2.0 V and VIL = 0.8 V)



Jitter vs Frequency (3.3 V, Room Temp, VIH = 2.0 V and VIL = 0.8 V)



Figure 3. Peak-to-Peak and RMS Jitter of CDCV304 Driver Output (Point 2)

Peak-Peak Jitter vs Frequency (3.3 V, VIH = 2.0 V and VIL = 0.8 V)



Figure 4. Peak-to-Peak Jitter of CDCV304 Driver Output (Point 2 Over Industrial Temperature Range)

Figure 4 shows that temperature has negligible impact on jitter performance of the CDCV304 clock driver.

Test Equipment Setup for Driving Backplane Transceiver





In this setup, the CDCV304 is used to provide the input clock for TI's backplane transceiver. The main objective of performing this experiment is to observe how TI's backplane transceiver performs when driven by the CDCV304 clock driver.

Recommended Termination for CDCV304 Clock Driver



Figure 6. Series Termination for CDCV304 Clock Driver

Usually the value of the characteristic impedance (Z_0) lies between 50 Ω and 70 Ω .

Typical impedance for this LVCMOS output is 20 Ω .

Series termination (with a 30- Ω resistor) is recommended to terminate the driver outputs.

This clock driver can drive a 10-pF capacitive load. Because the input load of TI's backplane receiver is only 4 pF, the CDCV304 is capable of driving multiple loads of the backplane transceivers.

Test Summary

The following graphs (Figures 7, 8, 9, and 10) illustrate the worst case peak-to-peak and RMS jitter measurements taken at various points as indicated in Figure 5. Point 1 is the output jitter of the corresponding HP8133A frequencies. Point 2 is the output jitter of the CDCV304 when driven by the HP clock source. Point 3 is the output jitter at the end of the chain, where the transceiver is driven by the CDCV304 clock driver.

Jitter Performance of CDCV304 + TLK1201 Combination





Jitter Performance of CDCV304 + TLK1501 Combination



Jitter Comparison at Different Stages (Nominal Supply and Room Temperature)

Figure 8. Jitter Values at Different Points Shown in Figure 5 With TLK1501

Jitter Performance of CDCV304 + TLK2501 Combination





Jitter Performance of CDCV304 + TLK3101 Combination



Figure 10. Jitter Values at Different Points Shown in Figure 5 With TLK3101

Conclusion

The graphs above show that the CDCV304 adds less than 20 ps of peak-to-peak jitter to its buffered outputs. The clock output jitter is less than 40 ps, which is the maximum jitter tolerance of the clock input of the aforementioned backplane transceivers, over the data-sheet-specified frequency and temperature range. Consequently, the CDCV304 clock driver satisfies all specified requirements for the input clock and can be used to drive any of these backplane transceivers.

Table 1.	Recommended	Clock Drivers fo	or Serial /	Gigabit Transceivers
----------	-------------	-------------------------	-------------	-----------------------------

Serial / Gigabit Transceiver	Recommended CDC Clock Drivers
SLK2501	CDCVF111 up to 622.08 MHz
	CDC111 up to 500 MHz
TLK3104A	CDC111 and CDCVF111
TLK3104SC	CDCVF111 up to 622.08 MHz
	CDC111 up to 500 MHz
TLK1201, TLK1501, TLK2201, TNETE2201B, TLK2501, TLK2701, TLK2711, TLK3101	CDCV304 up to 140 MHz
TLK3114SA	CDC111/CDCVF111

TEXAS INSTRUMENTS

References

- 1. CDCV304 140-MHz PCI-X Clock Buffer data sheet, Texas Instruments, 2000 (SCAS643)
- 2. Clock Distribution Circuits (CDC) Data Book, Texas Instruments, 1999 (SCAD004)
- 3. *TLK1201RCP, TLK1201IRCP Ethernet Transceivers* data sheet, Texas Instruments, 2001 (SLLS506)
- 4. TLK1501 0.6 to 1.5 Gbps Transceiver data sheet, Texas Instruments, 2001 (SLLS428)
- 5. TLK2201, TLK22011 Ethernet Transceivers data sheet, Texas Instruments, 2001 (SLLS420)
- 6. TLK2501 1.5 to 2.5 Gbps Transceiver data sheet, Texas Instruments, 2001 (SLLS427)
- 7. TLK2701 1.6 to 2.7 Gbps Transceiver data sheet, Texas Instruments, 2000 (SLLS429)
- 8. TLK2711 1.6 to 2.7 Gbps Transceiver data sheet, Texas Instruments, 2001 (SLLS501)
- 9. TLK3101 2.5 Gbps to 3.125 Gbps Transceiver data sheet, Texas Instruments, 2001 (SCAS649)

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DSP	dsp.ti.com	Broadband	www.ti.com/broadband
Interface	interface.ti.com	Digital Control	www.ti.com/digitalcontrol
Logic	logic.ti.com	Military	www.ti.com/military
Power Mgmt	power.ti.com	Optical Networking	www.ti.com/opticalnetwork
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
		Telephony	www.ti.com/telephony
		Video & Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments

Post Office Box 655303 Dallas, Texas 75265

Copyright © 2006, Texas Instruments Incorporated